


Laser cutting machine manufacturing process

1. Laser cutting machine process flow chart



2. Factory Panorama



3. Machine tool frame process steps

3.1 Raw material display of rack steel plate:



3.2 Shot blasting machine to deal with impurities on the surface of steel plate:



3.3 CNC plasma cutting steel plate according to drawings:



3.4 Machine frame welding:



3.5 The racks are processed through a large tempering furnace:



3.6 Impurities on the surface of the rack after sandblasting:



3.7 The frame is processed by CNC floor boring and milling:




3.8 Processing of other machine parts:





3.9 Assembly Machine:



3.91 Assembly accuracy inspection:



4. Laser cutting machine assembly room display

4.1 Small and medium-sized laser cutting machine assembly room display:







4.2 Large-size laser cutting machine assembly room display:





5.Contact Us

